

VME BPM - Bug #10044

Some BPMs are incorrectly mapped for TG9

09/03/2015 04:17 PM - John Diamond

Status:	Closed	Start date:	09/03/2015
Priority:	Normal	Due date:	
Assignee:	John Diamond	% Done:	100%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.25 hour
Description			

History

#1 - 09/03/2015 04:22 PM - John Diamond

Found that the BPMs attach to the digitizer's at base 0x2000 and 0x3000 were swapped in the startup script.

#2 - 09/03/2015 04:22 PM - John Diamond

- Status changed from New to Resolved

- % Done changed from 0 to 100

#3 - 09/04/2015 12:39 PM - John Diamond

- Status changed from Resolved to Closed